SIEMENS



Access Control
SiPass® integrated MP2.65

Product Release Notes
Addendum

MP2.65 SP4

Copyright

Technical specifications and availability subject to change without notice.

© Copyright Siemens Switzerland Ltd.

We reserve all rights in this document and in the subject thereof. By acceptance of the document the recipient acknowledges these rights and undertakes not to publish the document nor the subject thereof in full or in part, nor to make them available to any third party without our prior express written authorization, nor to use it for any purpose other than for which it was delivered to him.

Edition: 12.2016

Document ID: A-100083-1

Contents

3	Known Issues	5
2.2	Microsoft SQL Server	4
2.1	Microsoft Windows 10	4
2	Supported Systems	4
1	Introduction	4

1 Introduction

This addendum includes information regarding operation of SiPass[®] integrated with Microsoft Windows 10 and Microsoft SQL Sever 2014. Any unresolved issues are listed in the *Known Issues* section.

2 Supported Systems

The following are now supported:

2.1 Microsoft Windows 10

Windows 10 Enterprise	✓
Version 10.0.10240 Build 10240	

2.2 Microsoft SQL Server

Microsoft SQL Server 2014 - 12.0.4100.1 (X64)	✓

3 Known Issues

The issues listed below are regarding operation of SiPass integrated MP2.65 SP4 with MS Windows 10.

For more information on Known Issues for the MP2.65 SP4 base release, or any previous releases, refer to the Release Notes document respective to that release.

Summary	Issue
 Addition of a SiPass client node installed in Windows 10 Operating System to the existing running system - SiPass Server in Windows 2012 Database Backup and restore on 	Some issues regarding display of column headers in Audit Trail, Alarm Queue and Message Queue dialogs.
MS SQL Server 2014	
Localization (German)	
Database Backup and restore on MS SQL Server 2008 R2	Windows 10 incompatible with SQL Server 2008 and SQL Server 2008 R2, as confirmed by Microsoft.
Database Backup and restore on MS SQL Server 2012	SiPass integrated Remote Client login fail with MS SQL Sever 2012. Note: Not recommended for multi-node installation environment.

Issued by
Siemens Switzerland Ltd
Building Technologies Division
International Headquarters
Gubelstrasse 22
CH-6301 Zug
www.siemens.com/ buildingtechnologies

 $\hbox{@ Siemens Switzerland Ltd 2016}$ Technical specifications and availability subject to change without notice.

Document no.A-100083-1Product Release NotesEdition12.2016CPS Fire Safety